







# Displays

## Head Mounted Displays

HBS 16000		HBS 16000/X		HBS 16001	
					
Input	PRT / Thermocouple	Input	PRT / Thermocouple	Input	4...20 mA
Supply	AA Battery Powered	Supply	AA Battery Powered	Supply	Loop Powered
Communication	No	Communication	No	Communication	No
Certified	No	Certified	Exia	Certified	No

HBS 16001/X		HBS 16002		HBS 16002/X	
					
Input	4...20 mA	Input	PRT	Input	PRT
Supply	Loop Powered	Supply	AA Battery Powered	Supply	AA Battery Powered
Communication	No	Communication	No	Communication	No
Certified	Exia	Certified	No	Certified	Exia

HBS 16003		HBS 16003/X		HBS 16004/X	
					
Input	4...20 mA	Input	4...20 mA	Input	4...20 mA
Supply	Loop Powered	Supply	Loop Powered	Supply	Loop Powered
Communication	No	Communication	No	Communication	HART®
Certified	No	Certified	Exia	Certified	Exia

## Panel Mounted Displays

5331A		5531B		5714	
					
Input	4...20 mA	Input	4...20 mA	Input	PRT / Thermocouple / $\Omega$ / mA / V
Supply	Loop Powered	Supply	Loop Powered	Supply	AC / DC
Communication	No	Communication	No	Communication	No
Certified	No	Certified	Exia	Certified	No

5715		5725	
			
Input	PRT / Thermocouple / Ohms / mA / V	Input	kHz / $\mu$ S
Supply	AC / DC	Supply	AC / DC
Communication	No	Communication	No
Certified	No	Certified	No